


GASTESTER ADJUSTMENT PROCEDURE

TO SET ZERO POINT

POWER UP GASTESTER AND ALLOW TO WARM UP FOR AT LEAST 5 MINUTES

DO NOT ADJUST POTS "C" OR "D"



TURN POT "A" FULLY ANTI-CLOCKWISE.

ADJUST POT "B" UNTIL DISPLAY READS ZERO.

TURN POT "A" FULLY CLOCKWISE AND MAKE A NOTE OF THE DISPLAY READING.

CALCULATE ZERO POINT.

$\text{ZERO POINT} = (\text{DISPLAY READING} / 2) - 2$

ADJUST POT "A" UNTIL THE DISPLAY EQUALS ZERO POINT.

ADJUST POT "B" UNTIL THE DISPLAY READS 00.0